



LENCO REPLACEMENT ACTUATORS FOR SKI BOATS & TOW BOATS



FINDING YOUR LENCO MARINE REPLACEMENT ACTUATOR

REVISED OCT 2014

Follow these simple steps to find your 12 Volt Replacement Actuator

A

Find the code on face of the actuator below the Lenco label. The second digit from the left identifies the Actuator Type. Follow the arrow from step A on the chart below.

B

The first digit to the left represents either 3 or 5 lobes in the motor. 1-4 from code = 3 Lobes 5-8 from code = 5 Lobes Follow the arrow from step B on the chart below.

C

The last digit to the far right of the code identifies the hole size(s) for mounting. Follow the arrow from step C on the chart below.

The additional space is the only difference found between the old & new 5 digit code.

OLD BRANDING CODE (5 digit code used prior to 2013)



NEW BRANDING CODE (5 digit code used 2013 forward)



A

B

C

Location of the imprinted branding code [x x x x x] or [x _ x x x x]



Your existing actuator

Actuators include 6' wire leads & Deutsch connectors.

Replacement Part #	OEM #	Type code	Lobes code	Hole code	Actuator	Voltage	Stroke Length	Top Hole	End Hole
N/A **	20400-0013	A	1-4	1	101 Standard Actuator	12V	2.25"	5/16"	5/16"
15054-001	20400-001	A	5-8	1	101 Standard Actuator	12V	2.25"	5/16"	5/16"
N/A **	20401-0013	C	1-4	2	101XD Actuator	12V	2.25"	5/16"	5/16"
15055-001	20401-001	C	5-8	2	101XD Actuator	12V	2.25"	5/16"	5/16"
15117-001 **	20402-0013	E	1-4	2	101XDS Actuator	12V	2.25"	5/16"	5/16"
15057-001	20402-001	E	5-8	2	101XDS Actuator	12V	2.25"	5/16"	5/16"
15059-001	20403-001	F	5-8	1	102S Actuator	12V	4.25"	5/16"	5/16"
N/A **	20740-0023	L	1-4	1	1.25 XDS Actuator	12V	1.25"	5/16"	5/16"
15132-001	20740-002	L	5-8	1	1.25 XDS Actuator	12V	1.25"	5/16"	5/16"
15129-001	20990-001	V	5-8	1	102F Actuator (Fast)	12V	4.25"	5/16"	5/16"
15118-001 **	20791-0013	P,I,J	1-4	2	102HD Actuator	12V	4.25"	5/16"	5/16"
15060-001	20791-0015	P,I,J	5-8	2	102HD Actuator	12V	4.25"	5/16"	5/16"
15119-001 **	20740-0013	T*,L	1-4	2	1.25 XDS Actuator	12V	1.25"	5/16"	5/16"
15120-001	20740-001	T*,L	5-8	2	1.25 XDS Actuator	12V	1.25"	5/16"	5/16"
15121-001 **	20740-003	N,L	1-4	4	1.25 XDS Actuator	12V	1.25"	5/16"	3/8"
15122-001	20740-0035	N,L	5-8	4	1.25 XDS Actuator	12V	1.25"	5/16"	3/8"
15130-001	20991-011	W	5-8	2	102 HD Actuator (Fast)	12V	4.25"	5/16"	5/16"

* If your Malibu actuator contains the letter T in the branding code call Lenco Marine Customer Service at (772) 288-2662.

** This (3) lobe actuator is discontinued and no longer available. Please refer to the (5) Lobe Actuator Upgrade Conversion Guide to identify replacement products for older boats with (3) lobe actuators. For more information please contact Lenco Marine Customer Service at (772) 288-2662. All (3) lobe actuators were manufactured 2011 and prior. All (5) lobe actuators were manufactured 2012 and later.

	Ski / Tow Boat	Actuators used
OEM Quick Reference	Correct Craft / Nautique	15060-001, 15057-001
	Calabria	15117-001, 15057-001
	Epic Boats	15117-001 (Center), 15057-001 (Center), 15060-001 (Surf)
	Fineline / Ski Centurion	15119-001 (Center), 15120-001 (Center), 15055-001 (Center), 15060-001
	Malibu / Axis	15118-001 (PW), 15060-001 (PW), 15059-001 (Surf Gate), 15129-001 (Surf Gate)
	MasterCraft	15117-001, 15057-001, 15119-001, 15120-001, 15060-001, 20401-0013 (OEM#)
	MB Sports / TOMCAT / B52	15117-001, 15057-001
	Skier's Choice / Supra / Moomba	15121-001, 15122-001, 15130-001
	Tige	20400-0013 (OEM#), 20740-0023 (OEM#), 15054-001, 15132-001